

Defining Glass Quality Since 1927

Revision: 0

Dustin Sanders E Dillon & Company PO Box 160

Swords Creek, VA 24649

Order #:

A16448

PO #: Entered:

26815 06/29/2022

Page 1 of 1

Completed:

07/16/2022

Analysis of Dolomite

Description	060222
Sample ID	A16448-1
% Decrepitation	0.7, 0.8
% Ni	< 0.0005

If the sample received from the customer was removed from a larger quantity of material, the sample must be representative of that quantity for the results to be applicable. Decrepitation was determined in duplicate for quality assurance purposes.

Method Summary:

Prep: MA-0015 Rev. 0

Decrepitation: Gravimetric (AM-I-0036 Rev. 1)

Ni: ICP (LP-0142 Rev. 1)

References:

PFNB-381/30 A-219/93-94 A-233/75

Prepared By:

Canice R. Bielski

Senior Chemist

Reviewed/Approved B

Manager